


Figure 1



Pore size distribution plot

D-H method (Free adsorption branch)

Figure 2





Figure 3



Pore size distribution plot

D-H method (Free adsorption branch)